

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

TURPENTINE & ROSIN FACTORS, INC., OFFICE AND
WAREHOUSE
Lamar Ward
Savannah
Chatham County
Georgia

HABS GA-2393

HABS

GA-2393

INDEX TO BLACK AND WHITE PHOTOGRAPHS

✱ William Brockenbrough, photographer, June 2007

- | | |
|------------|---|
| GA-2393-1 | View of warehouse from former location of St. Julian Street, facing southwest |
| GA-2393-2 | View of warehouse from south of President Street, facing northeast |
| GA-2393-3 | View from north side of warehouse towards city, facing west |
| GA-2393-4 | North (front) facade, 1937 office building |
| GA-2393-5 | North (front) facade, 1937 office building, with 8' scale |
| GA-2393-6 | Northeast quarter |
| GA-2393-7 | East (side) facade of 1937 office building, with 8' scale |
| GA-2393-8 | East (side) facade of 1921 warehouse, with 8' scale |
| GA-2393-9 | View of east (side) facade of warehouse and office building |
| GA-2393-10 | Southeast quarter |
| GA-2393-11 | South (rear) facade of 1921 warehouse, with 8' scale |
| GA-2393-12 | Southwest quarter |
| GA-2393-13 | Northwest quarter |
| GA-2393-14 | Front entrance showing door surround and front steps |
| GA-2393-15 | Detail of northeast corner showing quoins |

TURPENTINE & ROSIN FACTORS, INC., OFFICE AND

HABS GA-2393
INDEX TO PHOTOGRAPHS

PAGE 2

GA-2393-16	Detail view of front facade showing parapet and corbelled brick
GA-2393-17	View of windows on east elevation of 1921 warehouse
GA-2393-18	View of turpentine tank foundations, facing southwest
GA-2393-19	Interior view, looking south, of front entrance hall
GA-2393-20	Interior view, looking southwest, of front office showing fireproof file room and dumbwaiter
GA-2393-21	Interior view, looking southwest, of first floor office with loading bay visible through window
GA-2393-22	Interior view, looking southeast, of loading bay
GA-2393-23	Interior view, looking west, of main second floor office space
GA-2393-24	Interior view, looking north, of door opening on second floor main office space
GA-2393-25	Interior view, looking north, of door opening on second floor main office space
GA-2393-26	Interior view of warehouse, facing south
GA-2393-27	Interior view of warehouse, facing north